
Software Release Notes

HS Series version 1.4.0

This document describes the changes from HS Series version 1.3.0 to version 1.4.0.



After updating the firmware, perform a **Factory Reset**. For more information on performing a **Factory Reset**, refer to *HS Series User Guide (P/N: 020-000883-XX)*.

Affected products

The following products are affected:

- D13HD-HS
- D13WU-HS
- D13HD-HS China
- D13WU-HS China

Purpose of release

The primary purpose of this software release is:

- Updated to a custom logo.
- Fixed a right-side of the image flicker issue.

Technical support

Technical support for Christie products is available at:

- North and South America: +1-800-221-8025 or Support.Americas@christiedigital.com
- Europe, Middle East, and Africa: +44 (0) 1189 778111 or Support.EMEA@christiedigital.com
- Asia Pacific: +65 6877-8737 or Support.APAC@christiedigital.com